BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Providing and laying HDPE water line in Mohankumar nagara Block 3 in JP Park ward 17
2	Administration Approval & Date	JC/RRN/AS/2255/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/302/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,97,000/-
5	Job Code No.	017-14-000023
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/225/13-14 Dtd: 06.02.2014
8	Work order Number & Date	EE/RRND/WO/225/13-14 Dtd: 06.02.2014
9	Contract Amount as per Agreement	Rs. 53,46,702/-
10	Bill Amount	
11	B.R No. & Date	199/14-15 Dtd: 31.05.2014
12	Agency	M/s Damodar & Co.
13	M.B. Number & Page No. of Measurement records	118/13-14 Page No 11735 to 11741
14	Date of Inspection	06.09.2017
15	Enclosures	4. Number of photos taken during inspection
16	I have Inspected the above site locations along with the Concerned person as per EE(RRND) Letter No EE(RRN)/PR/414/A/17-18 Dated 1-9-2017. It is observed that the Items indicated in the ~~MB~~ Xerox Copy of MB/XL sheets are not susceptible for measurements, as such the portion taken during the execution of work have been scrutinized and Inspected, it appears that the above work has been done. This is a reference to the NOC Issued by Lokayukta vide letter No LOK/INV(T)/CT/Crime/60/2014 Dated 1-8-2017	

Inspection Report

6/9/2017
(R. Sathyanarayana)
Inspection Report Officer.

R. SATHYANARAYANA
INSPECTION OFFICER

EE (RRN) Division, RR Nagara Zone.

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು - ....

Scanned by CamScanner